## **BUILDING SAFETY CERTIFICATE**

NO BE

Dated: 07/07/2025

it is certified that the existing building LITTLE FLOWER SCHOOL PANDHURNA (name of the building or premises) at ... PANDHURNA/ M.P.) (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in	Block	Block	Block	
school	(1)	(2)	(3)	
No. of Floor(s) in the	03	03	03	
Block				

The building is owned/occupied by LITTLE FLOWER SCHOOL PANDHURNA (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of P.W.D (Name of Department/ Govt.) on...9.7/25(date of inspection) in the presence of Rajesh Dudhe ..... (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 07/07/2025 for a period of 08/07/2026 years in accordance with rule and subject to compliance of the specific conditions as appended

1.BLOCK A FLOOR -3 GOOD CONDITION

2.BLOCK B FLOOR -3 GOOD CONDITION

3.BLOCK B FLOOR -3 GOOD CONDITION

Signature with Seal:

Name: Rigish Dudhe

Designation: Sub Engineer

Name&Address of Department/ Office:

P.W.D. Parelhatine